


PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

PART-1

(To be filed by the Head of School/Institute)


- | | | |
|----|--|--|
| 1 | Name of the School | MAHARISHI VIDYA MANDIR-V |
| 2 | Location | GOTANAGAR, JALUKBARI
GUWAHATI-781033 |
| 3 | Plot Area | 4 Bigha (5353.159 Sq. meter) |
| 4 | Plinth Area | 187.69 x 3 nos. = 563.07 Sq.m. |
| 5 | Numbers of Storey's | G + 4th Storey's |
| 6 | Year of Construction of Building | 2019 |
| 7 | If the building has been constructed under the supervision of the qualified Engineer, the following details may be given | |
| a) | Name of the Engineer with qualification | Mr. Amitav Sarma B.E Arch. |
| c) | Address of Engineer | Rehabari, Guwahati |
| c) | Set of Structural drawing used in the construction , if available | |
| d) | Name & address of Architect with qualification | Mr. Amitav Sarma B.E Arch.
Rehabari, Guwahati |
| 8 | Whether the building has been Constructed for the puepose | |
| a) | School | <input checked="" type="checkbox"/> YES/NO <input checked="" type="checkbox"/> |
| b) | Residential purpose and converted for use as a School | YES/NO <input checked="" type="checkbox"/> |
| 9 | Materials used for roof | |
| a) | R.C.C. Slabs/R.B.C Slabs | <input checked="" type="checkbox"/> YES/NO <input checked="" type="checkbox"/> |
| b) | R.S. Joist & Battons | YES/NO <input checked="" type="checkbox"/> |
| c) | Wooden joists & Battons | YES/NO <input checked="" type="checkbox"/> |
| 10 | Materiels used for Walls | |
| a) | Mud Mortar | YES/NO <input checked="" type="checkbox"/> |
| b) | Cement Mortar | <input checked="" type="checkbox"/> YES/NO <input checked="" type="checkbox"/> |
| c) | Lime Mortar | YES/NO <input checked="" type="checkbox"/> |
| 11 | Flooring | |
| a) | Conglomerate | <input checked="" type="checkbox"/> YES/NO <input checked="" type="checkbox"/> |
| b) | Terrazo | YES/NO <input checked="" type="checkbox"/> |
| c) | Brick paving | <input checked="" type="checkbox"/> YES/NO <input checked="" type="checkbox"/> |
| 12 | A details drawing including dimensions of the rooms
Alongwith size and location of doors and windows
(Attached) | |


Signature with Stamp of the Seal
of the School/Institution
Principal
MVM-V, Gotanagar
Guwahati-33

PARI-II
(To be filled by the S.D.E)

- a) I have visited the above mentioned school on dated 03/08/2022
And have visually inspected it from all angles of safety and if find it fit for normal use as School building
- b) In case any addition / alteration or expansion and modification to this building is to be carried out the reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use up to (indicate upto which it can be used)


Assit. Executive Engineer, PWD
Guwahati West Territorial Building
Sub-Division, Jalukbari, Guwahati-13
Signature with Stamp of the Seal
Sub Divisional Engineer.(S.D.E)


PRINCIPAL
MAHARISHI VIDYA MANDIR-V
GOTANAGAR, GUWAHATI-33
Principal
MVM-V, Gotanagar
Guwahati-33